


## GNM 21 - G 4A

### DC Geared Motors with permanent magnet field

Motor series GNM 21  
Spur gear series G 4A  
**up to 4 Nm**



Type	Gear Ratio	Dimension		
		a	b	c
GNM 2130C	360:1 - 9720:1	139	58	26
GNM 2145C	60:1 - 90:1	140	44	15
GNM 2145C	120:1 - 270:1	154	58	26

type	GNM 21 - G 4A
series	C
operation acc. to standards	VDE 0530
isolation acc. to standards	VDE 0530
protection acc. to standards	VDE 0530
kind of connection	
rotating direction	
bearing (motor)	S1
bearing (gear box)	F

IP 21  
free leads  
reversible  
ball bearing  
friction bearing

#### **Motor design:**

Pinion pressed on the motor shaft. Free leads.  
Foot or flange mounting with 4 threads, see drawing.

#### Rotating direction:

The rotating direction can be changed by inverting the connections.

#### Order example

Motor	- gear box
GNM 2145C	- G 4A
24 V, 6000 rpm	- 60:1

**GNM 21C - G4A**

load limitations gear box																			
1 nominal voltage	2 nominal speed	3 nominal torque	4 starting torque	5 nominal torque at undulatory current	6 nominal power	7 nominal current	8 nominal current at undulatory current	9 peak current	10 power gear box input	11 nominal speed gear box input	12 ratio gear box	13 efficiency gear box	14 max. power	15 max. cont. torque	16 max. starting torque	17 total weight motor + gear box	18 F <sub>R</sub> (allow. radial shaft load)	19 F <sub>A</sub> (allow. axial shaft load) <sup>1)</sup>	20 motor type
V	rpm	Nm	Nm	Nm	W	A	A	A	W	rpm	i	%	W	Nm	Nm	kg	N	Z	
12	100	0,80 <sup>2)</sup>	1,5 <sup>2)</sup>	0,55	8,4	1,9 <sup>2)</sup> 1,0 <sup>2)</sup>	1,5 0,81	3,4 <sup>2)</sup> 1,8 <sup>2)</sup>	13	6000	60:1	65	8,4	0,80	1,5	1,2	20	0	GNM 2145C
24																			
12	67	1,2 <sup>2)</sup>	2,0 <sup>2)</sup>	0,83	8,4	1,9 <sup>2)</sup> 1,0 <sup>2)</sup>	1,5 0,81	3,1 <sup>2)</sup> 1,6 <sup>2)</sup>	13	6000	90:1	65	8,4	1,2	2,0	1,2	20	0	
24																			
12	50	1,5 <sup>2)</sup>	2,5 <sup>2)</sup>	1,0	7,9	1,9 <sup>2)</sup> 1,0 <sup>2)</sup>	1,5 0,81	2,9 <sup>2)</sup> 1,5 <sup>2)</sup>	13	6000	120:1	60	7,9	1,5	2,5	1,2	20	0	
24																			
12	33	2,0 <sup>2)</sup>	3,0 <sup>2)</sup>	1,4	7,0	1,9 <sup>2)</sup> 0,99 <sup>2)</sup>	1,5 0,81	2,5 <sup>2)</sup> 1,3 <sup>2)</sup>	13	6000	180:1	55	7,0	2,0	3,0	1,2	20	0	
24																			
12	25	2,5 <sup>2)</sup>	4,0 <sup>2)</sup>	1,9	6,5	1,8 <sup>2)</sup> 0,95 <sup>2)</sup>	1,5 0,81	2,5 <sup>2)</sup> 1,3 <sup>2)</sup>	12	6000	240:1	55	6,5	2,5	4,0	1,2	20	0	
24																			
12	22	2,5 <sup>2)</sup>	4,0 <sup>2)</sup>	2,1	5,8	1,7 <sup>2)</sup> 0,89 <sup>2)</sup>	1,5 0,81	2,3 <sup>2)</sup> 1,2 <sup>2)</sup>	11	6000	270:1	55	5,8	2,5	4,0	1,2	20	0	
24																			
12	17	2,5 <sup>2)</sup>	4,0 <sup>2)</sup>	2,0	4,4	1,3 <sup>2)</sup> 0,63 <sup>2)</sup>	1,2 0,56	1,8 <sup>2)</sup> 0,87 <sup>2)</sup>	8,0	6000	360:1	55	4,4	2,5	4,0	1,1	20	0	GNM 2130C
24																			
12	13	2,6 <sup>2)</sup>	4,0 <sup>2)</sup>	2,4	3,4	1,2 <sup>2)</sup> 0,58 <sup>2)</sup>	1,2 0,56	1,6 <sup>2)</sup> 0,76 <sup>2)</sup>	6,8	6000	480:1	50	3,4	2,6	4,0	1,1	20	0	
24																			
12	11	2,6 <sup>2)</sup>	4,0 <sup>2)</sup>	2,6	3,0	1,1 <sup>2)</sup> 0,52 <sup>2)</sup>	1,1 0,52	1,4 <sup>2)</sup> 0,66 <sup>2)</sup>	5,5	6000	540:1	55	3,0	2,6	4,0	1,1	20	0	
24																			
12	8,3	2,8 <sup>2)</sup>	4,0 <sup>2)</sup>	2,8	2,4	1,0 <sup>2)</sup> 0,49 <sup>2)</sup>	1,0 0,49	1,2 <sup>2)</sup> 0,59 <sup>2)</sup>	4,9	6000	720:1	50	2,4	2,8	4,0	1,1	20	0	
24																			
12	6,3	2,8 <sup>2)</sup>	4,0 <sup>2)</sup>	2,8	1,8	0,95 <sup>2)</sup>	0,95	1,1 <sup>2)</sup> 0,45 <sup>2)</sup>	4,1	6000	960:1	45	1,8	2,8	4,0	1,1	20	0	
24																			
12	5,6	2,8 <sup>2)</sup>	4,0 <sup>2)</sup>	2,8	1,6	0,90 <sup>2)</sup>	0,90	1,1 <sup>2)</sup> 0,42 <sup>2)</sup>	3,6	6000	1080:1	45	1,6	2,8	4,0	1,1	20	0	
24																			
12	4,2	2,8 <sup>2)</sup>	4,0 <sup>2)</sup>	2,8	1,2	0,81 <sup>2)</sup>	0,81	0,93 <sup>2)</sup> 0,38 <sup>2)</sup>	2,7	6000	1440:1	45	1,2	2,8	4,0	1,1	20	0	
24																			
12	3,7	2,8 <sup>2)</sup>	4,0 <sup>2)</sup>	2,8	1,1	0,77 <sup>2)</sup>	0,77	0,88 <sup>2)</sup>	2,4	6000	1620:1	45	1,1	2,8	4,0	1,1	20	0	
24																			
12	2,8	3,0 <sup>2)</sup>	4,0 <sup>2)</sup>	3,0	0,87	0,72 <sup>2)</sup>	0,72	0,79 <sup>2)</sup>	1,9	6000	2160:1	45	0,87	3,0	4,0	1,1	20	0	
24																			
12	1,9	3,0 <sup>2)</sup>	4,0 <sup>2)</sup>	3,0	0,58	0,66 <sup>2)</sup>	0,66	0,70 <sup>2)</sup>	1,3	6000	3240:1	45	0,58	3,0	4,0	1,1	20	0	
24																			
12	1,4	3,0 <sup>2)</sup>	4,0 <sup>2)</sup>	3,0	0,44	0,64 <sup>2)</sup>	0,64	0,67 <sup>2)</sup>	1,1	6000	4320:1	40	0,44	3,0	4,0	1,1	20	0	
24																			
12	1,2	3,2 <sup>2)</sup>	4,0 <sup>2)</sup>	3,2	0,41	0,63 <sup>2)</sup>	0,63	0,66 <sup>2)</sup>	1,0	6000	4860:1	40	0,41	3,2	4,0	1,1	20	0	
24																			
12	0,9	3,2 <sup>2)</sup>	4,0 <sup>2)</sup>	3,2	0,31	0,60 <sup>2)</sup>	0,60	0,62 <sup>2)</sup>	0,78	6000	6480:1	40	0,31	3,2	4,0	1,1	20	0	
24																			
12	0,8	3,2 <sup>2)</sup>	4,0 <sup>2)</sup>	3,2	0,28	0,59 <sup>2)</sup>	0,59	0,61 <sup>2)</sup>	0,70	6000	7290:1	40	0,28	3,2	4,0	1,1	20	0	
24																			
12	0,6	3,2 <sup>2)</sup>	4,0 <sup>2)</sup>	3,2	0,21	0,58 <sup>2)</sup>	0,58	0,59 <sup>2)</sup>	0,53	6000	9720:1	40	0,21	3,2	4,0	1,1	20	0	
24																			

Tolerances ± 10 %

Columns 3 and 13  
Values are valid at operating temperature after run-in period.

Columns 5 and 8  
Current values should not exceed during operation with undulatory current (single way rectification) with harmonic portion above 5%.

Columns 4 and 9

Figures correspond with the gearbox load limitations. For high gear ratios the allowed currents may be lower than the motors rated current. If so, please the current has to be limited, e.g. through adjusting the servo controller.

Columns 14, 15 and 16

To avoid gear box overload do not exceed the mentioned values. For oscillating operation the mentioned limitations must be multiplied by 0,75.

<sup>1)</sup> middle of the shaft-extension

<sup>2)</sup> motor current must be limited to avoid excess of the mentioned value

design-changes reserved